



Woloski Park Roadway, flooded by approximately six feet of water in March 2010; Photo taken March 2010, looking due north toward the neighborhood. Airboat shown entering property to evacuate residents. Telephone poles indicate right of way.



Roadway in flood, showing canoes used for egress in flood conditions. Photo taken March 16, 2010, as residents evacuate after power is cut to their homes during first of the two major 2010 floods.



03/16/2010 10:58 AM

Floods costly to town in emergency response expenses; photo taken 3/16/2010 from side of Woloski Park road looking due north toward the neighborhood.



03/16/2010 12:58 AM

Floods costly to town in emergency response expenses; photo taken 3/16/2010 from northeast side of #4 Woloski Park, looking toward the southwest.



Flo

oods caused damage to homes and loss of property; Photo taken 3/19/2010.



F1

oods cause loss of utilities; Photo taken 3/16/2010.